

Toro offers an optional battery and charger giving you the freedom to print without an external power source.

The Toro battery is a Lithium-ion battery which conveniently mounts into the back of the Toro printer.

- 3 hours of continuous printing without a recharge.
- 30 hours in sleep mode in the printer without a recharge.
- 3 hours charge time if battery charge is below 10 percent.

The Toro battery is good for more than three-hundred lifetime charges and is warranted for 9 months from date of purchase.



Charging Unit

Battery Pack

NOTE: The Toro battery does not charge when in the printer. The charger is required.



Take Toro in the field.



Soft shell or hard shell travel cases are available

Toro Applications

Toro's versatility goes beyond its standalone independence and convenience. Toro software and thermal transfer printer give you nearly endless application possibilities.

DuraSuite™ Software

- Pipe Marking
- Arc Flash
- NFPA and RTK
- OSHA-ANSI Compliance
- Template and Chemical Library
- More than 1,300 Symbols

Q-Label Barcode Software

- Large barcode database
- Multiple Language Capability
- Command Code Generation
- Great for inventory management, sequencing and merging.

OpenOffice.org Label Writer

- Customize your own labels
- Wayfinding
- Lean Manufacturing
- Warehouse Identification
- Tool Cribs

With a print width range of ½" to 4" Toro can handle more than 40 DuraLabel specialty supplies.

